

protective garment

**GoodPRO FR9 Raptor**

PPE - category I

**Manufacturer:** GoodPRO, s.r.o., Dukelska 1247, 334 01 Prestice, Czech Republic, [www.goodpro.cz](http://www.goodpro.cz)


**Material:** 70% Tencel, 30% polyester, weight 210 g/m<sup>2</sup>

**Description:**

This protective garment provides a superior protection as well as excellent comfort. It is produced from the top-quality, harmless material and ensures a high level of abrasion resistance.

**Caution:**

To ensure the greatest possible protection and maintain its protective properties, the personal protective garment must be worn in compliance with the manufacturer's instructions, must be always well-fastened (all zippers and Velcro closures) and complete.

**Maintenance:**

Before washing zip up the garment, fasten all Velcro fasteners and take off the suspenders. We recommend washing at 40 °C with gentle machine wash, light spin, pH max.9. Use ordinary liquid detergents without any bleaching agents. Prewash excessively soiled garments. Rinse thoroughly and tumble dry at max spin speed 800 rpm. We recommend free drying in a warm room or drying in a dryer in 2 cycles (max 2x20min) at a lower temperature-max 60°C. Do not iron directly onto reflective tapes. HIGHER WASHING AND DRYING TEMPERATURES CAUSE FASTER WEAR OUT OF THE GARMENT!

**Storage:**

Store in dry and well-ventilated areas away from direct sunlight and UV rays. Protect from any damage.

**Notes:**

Keep the garment clean otherwise it can lead to the degradation of its properties. Check after every use. To ensure the greatest possible protection do not make any alternations to the garment and/or its design. The garment keeps its protective features only in the environment with standard volume of oxygen. To maintain the required level of protection, every two-part suits must be worn complete. Check and maintain the garment regularly. Manufacturer does not warrant nor shall manufacturer be liable, or in any way responsible, for damages to a product caused by abuse (including, but not limited to, improper use, lack of reasonable care and maintenance and/or any alteration). In case of any questions, please contact the manufacturer – [info@goodpro.cz](mailto:info@goodpro.cz) .

*You will find a Declaration of Conformity at [www.goodpro.cz](http://www.goodpro.cz)*